



Important product alert

Step2 Push Around Buggy and Whisper Ride Buggy

Step 2 have notified us that a batch of the Push Around Buggy and Whisper Ride Buggy have been manufactured with a yellow knob / pin that can become loose allowing the handle to separate from the buggy. If your buggy has a pin with a yellow plastic knob attaching the handle, please stop using it immediately.



Affected buggies have pins with yellow plastic knobs on the back of the buggy



Buggies as shown below with recessed handles attached with a bolt and screw are not affected.



If your buggy is affected please stop using immediately and contact Step2 for a repair kit on 0800 393159 between 9:00am and 5.00pm Monday to Friday or visit www.step2uk.com to receive a free repair kit.

This action has been taken to ensure the safety and well being of our customers and we apologise for any inconvenience this may cause.